



Environmental Testing, LLC

"Protecting You With Our Experience"

Limited Asbestos Sampling Report

Our Services:

- Asbestos Inspections
- Asbestos Abatement Design
- Asbestos Abatement Monitoring
- Asbestos Management Planning
- Mercury Vapor Assessments
- Radon Measurements
- Mold / IAQ Investigations
- Lead-Based Paint Inspections
- Hazardous Materials Assessments
- Asbestos Training Services

Marysville Water Plant
409 N. Main Street
Marysville, Ohio 43040

Prepared for:

City of Marysville
209 South Main Street
Marysville, Ohio 43040
(937) 645-7362

Report Date: June 19, 2023
Project Number: 23-232-004

Serving: Ohio | Indiana | Kentucky | Michigan

35 Compark Road, Suite 203, Dayton, Ohio 45459
937-751-7872 Office
www.daytontesting.com

June 19, 2023

Mr. Jeremy Hoyt, P.E.
Public Service Director
City of Marysville, Ohio
209 South Main Street
Marysville, Ohio 43040
(937) 645-7357
jhoyt@marysvilleohio.org

**Re: Limited Asbestos Sampling Report
Marysville Water Plant
409 N. Main Street
Marysville, Ohio 43040**

DET Project Number: 23-232-004

Dear Mr. Hoyt,

Dayton Environmental Testing, LLC (DET) has prepared this report to document the purpose, scope, methodology, and results of the limited asbestos sampling completed at the former Marysville Water Plant building located at 409 N. Main Street in Marysville, Ohio (Project Site).

PURPOSE AND SCOPE

The City of Marysville, Ohio (Client) requested that DET to perform asbestos sampling limited to routinely accessible building materials that could be safely sampled or sampled without extensive destructive methods. This sampling is strictly limited the materials and their locations described in the Asbestos Inspection and Assessment Summary provided in Attachment A. All other building materials and locations are excluded from this report.

This inspection was not completed for purposes renovation or demolition activities.

INSPECTION METHODOLOGY

DET Senior Project Manager and Ohio-certified Asbestos Hazard Evaluation Specialist Michael Lee conducted the asbestos sampling on May 30, 2023.

Samples were randomly collected from each homogeneous area sampled in accordance with the sampling procedures described under AHERA. Each sample was collected and

www.daytontesting.com

Office Address: 35 Compark Road, Suite 203, Dayton, Ohio 45459 | **Office Phone:** (937) 751-7872
Serving: Ohio | Indiana | Kentucky | Michigan

placed in a clean, sealable vial or sealed bag and labeled with a unique sample identification number. This sample number was recorded on an Asbestos Bulk Sampling Log and the sample vial or bag. Supplemental information was also recorded on the Asbestos Bulk Sampling Log, including inspection date, the building name (or number), a brief description and location of the sample, and the type of material sampled (e.g. ceiling tile). The Asbestos Bulk Sampling Log is included in Attachment B.

LABORATORY ANALYSIS

Samples collected by DET during this assessment were transported, under chain of custody, to Schneider Laboratories Global, Inc. (Schneider) in Richmond, Virginia for analysis. Schneider is fully accredited by the National Voluntary Laboratory Accreditation Program (NVLAP # 101150-0), the agency sponsored by the National Institute of Standards and Technology providing EPA accreditation of laboratories analyzing bulk samples for asbestos content by Polarized Light Microscopy (PLM) under AHERA.

Bulk samples were analyzed for asbestos content using EPA Method 600/M4-82/020, and when applicable EPA Method 600/R-93/116. Bulk sample analysis incorporates the use of stereoscopic microscopy and PLM coupled with dispersion staining. The analytical methods listed above, which the EPA currently recommends for the determination of asbestos in bulk samples of friable insulation materials, can be used for qualitative identification of six (6) morphologically different types of asbestos fibers: chrysotile, amosite, crocidolite, anthophyllite, tremolite, and actinolite asbestos.

The EPA method specifies that the asbestos content in a bulk sample shall be estimated and reported as a finite percentage (rounded to the nearest percent) within the range of 0 to 100. Minute quantities of asbestos in bulk samples may be reported as "trace" or less than 1 percent (<1%). The analytical method determined the "*area percent*" asbestos or the percentage of the area of a microscopic field of view that is occupied by asbestos fibers.

The results of bulk samples are reported in a standard written laboratory report. The written report includes the client name, the laboratory identification numbers assigned to each bulk sample upon receipt by the laboratory sample custodian, and the sample number assigned to each bulk sample during the building inspection. The composition of the bulk sample is reported in percentages of asbestos (i.e., chrysotile, amosite, crocidolite, or other) and non-asbestos (i.e., cellulose, fiberglass, synthetic, or other) components.

SUMMARY OF ASBESTOS

PLM bulk analysis indicated that the following material is ACM:

- 12" x 12" brown mottled floor tile located in the West Bay Area (patched area)

The following components were observed at the Project Site and may contain asbestos; however for safety reasons, these items were not assessed for ACM:

- Electrical systems components (various types - all suspect components in or on boxes, panels, boxes, wiring, cabling, etc.)
- Roofing materials (various types)
- Fire-rated doors (various types)
- Gaskets and packings
- Drinking fountain insulation
- Exhaust flues associated with gas heaters

PLM bulk analysis indicated that asbestos was not detected in any of the remaining samples collected from the Project Site.

Additional details of the materials assessed for asbestos during this sampling effort are summarized on the Asbestos Inspection and Assessment Summary in Attachment A. This summary includes where the material is located, material color, material description, the analytical result, and the estimated quantities of ACM, if applicable.

LIMITATIONS

The results and findings of this report are based on PLM bulk analysis only. Currently, federal and state regulations only require the use of PLM bulk analysis for compliance purposes; however, due to limitations of this analytical method to detect small fiber sizes and fibers obscured by cellulose and organic material, the EPA recommends transmission electron microscopy (TEM) confirmation for all organically bound non-friable material and cellulose containing ceiling tile samples found not to contain asbestos using PLM bulk analysis. Please notify DET within 30 days from the date of this report if you would like TEM confirmation for any samples.

CONCLUSIONS AND RECOMMENDATIONS

ACM identified during this assessment should only be removed by an Ohio-licensed Asbestos Hazard Abatement Contractor.

Prior to renovation or demolition activities, the National Emission Standards for Hazardous Air Pollutants (NESHAP) and Ohio regulations both require that all facilities be thoroughly inspected for the presence of asbestos.

This inspection was not completed for purposes renovation or demolition activities. Please contact DET for supplemental asbestos inspection services if this site will be renovated or demolished.

We sincerely appreciate the opportunity to provide this service to you and the City of Marysville. Please do not hesitate to contact me if you have any questions regarding this report, or if we can be of further assistance.

Respectfully,

Dayton Environmental Testing, LLC



Michael B. Lee
Senior Project Manager
Ohio Asbestos Hazard Evaluation Specialist # ES34954

ATTACHMENTS

- A - Asbestos Inspection and Assessment Summary
- B - Asbestos Bulk Sampling Log
- C – Building Floor Plans
- D - Laboratory Analytical Report
- E - Photographs
- F - Qualifications of Assessor
- G - Laboratory's NVLAP Certificate

ATTACHMENT A

ASBESTOS INSPECTION AND ASSESSMENT SUMMARY

HA ID #	Material	Description	Locations of Material	*Friable or Non-Friable	*NESHAP Category	Sample Numbers Collected	Photo #	Laboratory Results	Asbestos Determination	Estimated Quantity
1	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Various Locations Throughout Building	Non-Friable	Not Applicable	1-1 1-2 1-3 1-4 1-5	1	No Asbestos Detected	Non-ACM	Not Applicable
2	Floor Tile and Mastic	12" x 12" Light Gray with Tan Streaks Floor Tile and Yellow Mastic	Main Office	Non-Friable	Not Applicable	2-1 2-2	2	No Asbestos Detected	Non-ACM	Not Applicable
3	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Yellow Mastic	Main Office, Patch Area Near South Door	Non-Friable	Not Applicable	3-1 3-2	3	No Asbestos Detected	Non-ACM	Not Applicable
4	Carpet Mastic	Tan Mastic Associated with Carpeting	Main Office and 2nd Floor Office	Non-Friable	Not Applicable	4-1 4-2	4	No Asbestos Detected	Non-ACM	Not Applicable
5	Texture Compound	White Ceiling Texture Compound	Main Office Ceiling	Friable	Not Applicable	5-1 5-2 5-3	5	No Asbestos Detected	Non-ACM	Not Applicable (Sampling Less Than 1,000 Square Feet)
6	Floor Tile and Mastic	12" x 12" Tan Mottled Floor Tile and Black Mastic	West Bay Area	Non-Friable	Not Applicable	6-1 6-2	6	No Asbestos Detected	Non-ACM	Not Applicable
7	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Brown Mastic	West Bay Area, Northwest Patch Area	Non-Friable	Category I Non-Friable	7-1 7-2	7	Tile = 2% Chrysotile Asbestos Mastic = No Asbestos Detected	ACM	80 Square Feet
8	Sheet Flooring and Mastic	Black Sheet Flooring and Brown Mastic	Mechanical Room (Near Laboratory)	Non-Friable	Not Applicable	8-1 8-2	8	No Asbestos Detected	Non-ACM	Not Applicable
9	Flue Cement	Gray Flue Cement	Mechanical Room (Near Laboratory)	Non-Friable	Not Applicable	9-1 9-2	9	No Asbestos Detected	Non-ACM	Not Applicable
10	Desktop	Black Desktop and Sides	Laboratory	Non-Friable	Not Applicable	10-1 10-2	10	No Asbestos Detected	Non-ACM	Not Applicable
11	Sink Undercoating	Gray Sink Undercoating	Laboratory	Non-Friable	Not Applicable	11-1 11-2	11	No Asbestos Detected	Non-ACM	Not Applicable

HA ID #	Material	Description	Locations of Material	*Friable or Non-Friable	*NESHAP Category	Sample Numbers Collected	Photo #	Laboratory Results	Asbestos Determination	Estimated Quantity
12	Laboratory Counters	Black Laboratory Countertop, Backsplash, and Drywall Rack	Laboratory	Non-Friable	Not Applicable	12-1 12-2	12	No Asbestos Detected	Non-ACM	Not Applicable
13	Filler	Black Seam Filler Associated with Laboratory Countertop	Laboratory	Non-Friable	Not Applicable	13-1 13-2	13	No Asbestos Detected	Non-ACM	Not Applicable
14	Caulking	Tan Rubbery Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Most Upper Tank Area	Non-Friable	Not Applicable	14-1 14-2	14	No Asbestos Detected	Non-ACM	Not Applicable
15	Paint	Silver Paint	Mechanical Room (Near Laboratory)	Non-Friable	Not Applicable	15-1 15-2	15	No Asbestos Detected	Non-ACM	Not Applicable
16	Caulking and Mortar	White Caulking and Gray Mortar Associated with Steel Window Frames	Various Windows, South Building	Non-Friable	Not Applicable	16-1 16-2	16	No Asbestos Detected	Non-ACM	Not Applicable
17	Caulking	White Caulking Associated with Steel Window Frames	Various Windows, South Building	Non-Friable	Not Applicable	17-1 17-2	17	No Asbestos Detected	Non-ACM	Not Applicable
18	Window Glazing Compound	Gray Window Glazing Compound	Various Windows, South Building	Friable	Not Applicable	18-1 18-2	18	No Asbestos Detected	Non-ACM	Not Applicable
19	Caulking	Tan Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Middle Upper Tank Area	Non-Friable	Not Applicable	19-1 19-2	19	No Asbestos Detected	Non-ACM	Not Applicable
20	Window Glazing Compound	Tan Window Glazing Compound	Various Windows, South Building	Friable	Not Applicable	20-1 20-2	20	No Asbestos Detected	Non-ACM	Not Applicable
21	Ceiling Tile	2' x 4' Ceiling Tile (Brown with White Face)	Southeast Mechanical Room	Friable	Not Applicable	21-1 21-2	21	No Asbestos Detected	Non-ACM	Not Applicable
22	Mastic	Brown Mastic Associated with Wall Paneling	Southeast Mechanical Room	Non-Friable	Not Applicable	22-1 22-2	22	No Asbestos Detected	Non-ACM	Not Applicable

HA ID #	Material	Description	Locations of Material	*Friable or Non-Friable	*NESHAP Category	Sample Numbers Collected	Photo #	Laboratory Results	Asbestos Determination	Estimated Quantity
23	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom)	Friable	Not Applicable	23-1 23-2 23-3	23	No Asbestos Detected	Non-ACM	Not Applicable (Sampling Less Than 1,000 Square Feet)
24	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom	Friable	Not Applicable	24-1 24-2 24-3	24	No Asbestos Detected	Non-ACM	Not Applicable (Sampling Less Than 1,000 Square Feet)
25	Floor Tile and Mastic	12" x 12" Tan Speckled Floor Tile with Yellow Mastic	Restroom	Non-Friable	Not Applicable	25-1 25-2	25	No Asbestos Detected	Non-ACM	Not Applicable
26	Window Glazing Compound	Tan Window Glazing Compound	Windows Between Southeast Mechanical Area and Work Shop	Friable	Not Applicable	26-1 26-2	26	No Asbestos Detected	Non-ACM	Not Applicable
27	Attic Insulation	Gray Attic Insulation (Loose)	Attic	Friable	Not Applicable	27-1 27-2 27-3	27	No Asbestos Detected	Non-ACM	Not Applicable
28	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Various Locations Throughout Building	Non-Friable	Not Applicable	28-1 28-2 28-3 28-4 28-5 28-6 28-7	28	No Asbestos Detected	Non-ACM	Not Applicable (Sampling Area Over 5,000 Square Feet)
29	Floor Coating	Gray Floor Coating (Cementitious)	Laboratory	Non-Friable	Not Applicable	29-1 29-2	29	No Asbestos Detected	Non-ACM	Not Applicable
30	Caulking	Gray Window and Door Frame Caulking	Various Doors and Windows of North Building	Non-Friable	Not Applicable	30-1 30-2	30	No Asbestos Detected	Non-ACM	Not Applicable

HA ID #	Material	Description	Locations of Material	*Friable or Non-Friable	*NESHAP Category	Sample Numbers Collected	Photo #	Laboratory Results	Asbestos Determination	Estimated Quantity
31	Caulking	Gray Caulking Sealant	Exterior Tank Area Located on North Side of Buildings	Non-Friable	Not Applicable	31-1 31-2	31	No Asbestos Detected	Non-ACM	Not Applicable
32	Caulking	Off-White Caulking Associated with Newer Windows	Various Exterior Windows of South Building	Non-Friable	Not Applicable	32-1 32-2	32	No Asbestos Detected	Non-ACM	Not Applicable
33	Caulking	Off-White Caulking Associated with Doors	Various Exterior Doors of South Building	Non-Friable	Not Applicable	33-1 33-2	33	No Asbestos Detected	Non-ACM	Not Applicable
34	Caulking	Brown and Gray Caulking Associated with Door	Exterior Door, West Side of Building	Non-Friable	Not Applicable	34-1 34-2	34	No Asbestos Detected	Non-ACM	Not Applicable
35	Roofing Materials	Roofing Materials - Various Types	Roof	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	35	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos
36	Fire-Rated Doors	Fire-Rated Doors - Various Types	Various Locations Throughout Building	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	36	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos
37	Gaskets and Packings	Gaskets and Packings - Various Types	Various Locations Throughout Building	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	37	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos
38	Electrical Systems Components	Electrical Systems Components - Various Types	Various Locations Throughout Building	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	38	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos
39	Drinking Fountain Tank Insulation	Drinking Fountain Tank Insulation	Various Locations Throughout Building	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	39	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos
40	Gas Heater Exhaust Flue	Gas Heater Exhaust Flue	Various Locations Throughout Building	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	No Samples	40	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos	Not Assessed - May Contain Asbestos

ATTACHMENT B
ASBESTOS BULK SAMPLING LOG

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
1-1	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Main Office, Southeast Corner Wall	M. Lee
1-2	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Main Office, Northwest Corner Wall	M. Lee
1-3	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Office (Next to Bathroom), Southeast Corner Wall	M. Lee
1-4	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	2nd Floor Office, North Wall, Middle	M. Lee
1-5	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Laboratory, Southeast Corner Wall	M. Lee
2-1	2	5/30/2023	Floor Tile and Mastic	12" x 12" Light Gray with Tan Streaks Floor Tile and Yellow Mastic	Main Office, East Side, Middle	M. Lee
2-2	2	5/30/2023	Floor Tile and Mastic	12" x 12" Light Gray with Tan Streaks Floor Tile and Yellow Mastic	Main Office, East Side, North	M. Lee
3-1	3	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Yellow Mastic	Main Office, Near Entry Door	M. Lee
3-2	3	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Yellow Mastic	Main Office, Near Entry Door	M. Lee
4-1	4	5/30/2023	Carpet Mastic	Tan Mastic Associated with Carpeting	Main Office	M. Lee
4-2	4	5/30/2023	Carpet Mastic	Tan Mastic Associated with Carpeting	2nd Floor Office	M. Lee
5-1	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, Southeast Area	M. Lee
5-2	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, Northeast Area	M. Lee
5-3	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, West Side	M. Lee
6-1	6	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Mottled Floor Tile and Black Mastic	Open Area Outside Laboratory, East Side	M. Lee
6-2	6	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Mottled Floor Tile and Black Mastic	Open Area Outside Laboratory, North Side	M. Lee
7-1	7	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Brown Mastic	Open Area Outside Laboratory, Northwest Area	M. Lee
7-2	7	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Brown Mastic	Open Area Outside Laboratory, Northwest Area	M. Lee
8-1	8	5/30/2023	Sheet Flooring and Mastic	Black Sheet Flooring and Brown Mastic	Mechanical Room	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
8-2	8	5/30/2023	Sheet Flooring and Mastic	Black Sheet Flooring and Brown Mastic	Mechanical Room	M. Lee
9-1	9	5/30/2023	Flue Cement	Gray Flue Cement	Mechanical Room	M. Lee
9-2	9	5/30/2023	Flue Cement	Gray Flue Cement	Mechanical Room	M. Lee
10-1	10	5/30/2023	Desktop	Black Desktop and Sides	Laboratory, East Side	M. Lee
10-2	10	5/30/2023	Desktop	Black Desktop and Sides	Laboratory, East Side	M. Lee
11-1	11	5/30/2023	Sink Undercoating	Gray Sink Undercoating	Laboratory, Northwest Sink	M. Lee
11-2	11	5/30/2023	Sink Undercoating	Gray Sink Undercoating	Laboratory, Southwest Sink	M. Lee
12-1	12	5/30/2023	Laboratory Counters	Black Laboratory Countertop, Backsplash, and Drywall Rack	Laboratory, South Side	M. Lee
12-2	12	5/30/2023	Laboratory Counters	Black Laboratory Countertop, Backsplash, and Drywall Rack	Laboratory, North Side	M. Lee
13-1	13	5/30/2023	Filler	Black Seam Filler Associated with Laboratory Countertop	Laboratory, South Side	M. Lee
13-2	13	5/30/2023	Filler	Black Seam Filler Associated with Laboratory Countertop	Laboratory, North Side	M. Lee
14-1	14	5/30/2023	Caulking	Tan Rubbery Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Most Addition, West Side	M. Lee
14-2	14	5/30/2023	Caulking	Tan Rubbery Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Most Addition, East Side	M. Lee
15-1	15	5/30/2023	Paint	Silver Paint	Mechanical Room, North Wall	M. Lee
15-2	15	5/30/2023	Paint	Silver Paint	Mechanical Room, East Wall	M. Lee
16-1	16	5/30/2023	Caulking and Mortar	White Caulking and Gray Mortar Associated with Steel Window Frames	2nd Floor, Southwest Most Addition, North Wall, West Side	M. Lee
16-2	16	5/30/2023	Caulking and Mortar	White Caulking and Gray Mortar Associated with Steel Window Frames	2nd Floor, Southwest Most Addition, North Wall, East Side	M. Lee
17-1	17	5/30/2023	Caulking	White Caulking Associated with Steel Window Frames	2nd Floor, Southwest Middle Room, North Wall	M. Lee
17-2	17	5/30/2023	Caulking	White Caulking Associated with Steel Window Frames	2nd Floor, Southwest Middle Room, South Wall	M. Lee

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
18-1	18	5/30/2023	Window Glazing Compound	Gray Window Glazing Compound	2nd Floor, Southwest Most Addition, North Wall, West Side	M. Lee
18-2	18	5/30/2023	Window Glazing Compound	Gray Window Glazing Compound	2nd Floor, Southwest Middle Room, North Wall	M. Lee
19-1	19	5/30/2023	Caulking	Tan Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Middle Room, West Side	M. Lee
19-2	19	5/30/2023	Caulking	Tan Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Middle Room, East Side	M. Lee
20-1	20	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	2nd Floor Storage Room, West Wall	M. Lee
20-2	20	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	2nd Floor Mezzanine (Southwest Area), West Wall	M. Lee
21-1	21	5/30/2023	Ceiling Tile	2' x 4' Ceiling Tile (Brown with White Face)	Southeast Mechanical Room, Northeast Side	M. Lee
21-2	21	5/30/2023	Ceiling Tile	2' x 4' Ceiling Tile (Brown with White Face)	Southeast Mechanical Room, Northwest Area	M. Lee
22-1	22	5/30/2023	Mastic	Brown Mastic Associated with Wall Paneling	Southeast Mechanical Room, North Wall, West Side	M. Lee
22-2	22	5/30/2023	Mastic	Brown Mastic Associated with Wall Paneling	Southeast Mechanical Room, North Wall, East Side	M. Lee
23-1	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Northwest Area	M. Lee
23-2	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Middle Area	M. Lee
23-3	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Southeast Area	M. Lee
24-1	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, West Side	M. Lee
24-2	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, Middle	M. Lee
24-3	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, East Side	M. Lee
25-1	25	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Speckled Floor Tile with Yellow Mastic	Restroom (Near Door, North Side)	M. Lee
25-2	25	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Speckled Floor Tile with Yellow Mastic	Restroom (Near Door, South Side)	M. Lee
26-1	26	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	Southeast Mechanical Room, North Wall, East Side	M. Lee


Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
26-2	26	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	Southeast Mechanical Room, North Wall, West Side	M. Lee
27-1	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic (North)	M. Lee
27-2	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic (South)	M. Lee
27-3	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic, Middle	M. Lee
28-1	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, West Wall	M. Lee
28-2	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, East Wall	M. Lee
28-3	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, South Wall	M. Lee
28-4	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Work Shop, East Wall	M. Lee
28-5	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Work Shop, South Wall	M. Lee
28-6	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Northeast Large Bay, East Wall	M. Lee
28-7	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Northeast Large Bay, West Wall	M. Lee
29-1	29	5/30/2023	Floor Coating	Gray Floor Coating (Cementitious)	Laboratory (Near Door, West Side)	M. Lee
29-2	29	5/30/2023	Floor Coating	Gray Floor Coating (Cementitious)	Laboratory (Near Door, East Side)	M. Lee
30-1	30	5/30/2023	Caulking	Gray Window and Door Frame Caulking	North Building Window, North Side	M. Lee
30-2	30	5/30/2023	Caulking	Gray Window and Door Frame Caulking	North Building Window, West Side	M. Lee
31-1	31	5/30/2023	Caulking	Gray Caulking Sealant	North Side Basin Area	M. Lee
31-2	31	5/30/2023	Caulking	Gray Caulking Sealant	North Side Basin Area	M. Lee
32-1	32	5/30/2023	Caulking	Off-White Caulking Associated with Newer Windows	Exterior, East Side Window	M. Lee
32-2	32	5/30/2023	Caulking	Off-White Caulking Associated with Newer Windows	Exterior, South Side Window	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
33-1	33	5/30/2023	Caulking	Off-White Caulking Associated with Doors	Exterior, South Side Office Door	M. Lee
33-2	33	5/30/2023	Caulking	Off-White Caulking Associated with Doors	Exterior, South Side Mechanical Room Door	M. Lee
34-1	34	5/30/2023	Caulking	Brown and Gray Caulking Associated with Door	Exterior, West Side Door	M. Lee
34-2	34	5/30/2023	Caulking	Brown and Gray Caulking Associated with Door	Exterior, West Side Door	M. Lee


ATTACHMENT C
BUILDING FLOOR PLANS



N. Main Street

North →

Building Floor Plans Marysville Water Plant 409 N. Main Street, Marysville, Ohio 43040			
Sampling Dates: May 30, 2023			Floor : First Floor
Project #: 23-232-004	Scale: Not to Scale	Drawn By: MBL	PAGE
Dayton Environmental Testing, LLC		35 Compark Road, Suite 203 Dayton, Ohio 45459 (937) 751-7872 www.daytontesting.com	
		1 OF 2	



N. Main Street

North →

Building Floor Plans Marysville Water Plant 409 N. Main Street, Marysville, Ohio 43040			
Sampling Dates: May 30, 2023			Floor : Second Floor
Project #: 23-232-004	Scale: Not to Scale	Drawn By: MBL	PAGE
Dayton Environmental Testing, LLC		35 Compark Road, Suite 203 Dayton, Ohio 45459 (937) 751-7872 www.daytontesting.com	2
			OF
			2

ATTACHMENT D
LABORATORY ANALYTICAL REPORT



Analysis Report

Schneider Laboratories Global, Inc

2512 W. Cary Street • Richmond, Virginia • 23220-5117
804-353-6778 • 800-785-LABS (5227) • Fax 804-359-1475

Customer: Dayton Environmental Testing, LLC (4738)
Address: 35 Compark Rd
Suite 203
Dayton, OH 45459

Order #: 519082

Attn:

Received 06/06/23
Analyzed 06/13/23
Reported 06/13/23

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-001	05/30/23	1-1	Main Office SE Corner		
Layer 1:	Drywall			No Asbestos Detected	5% CELLULOSE FIBER
	White, Powdery				95% NON FIBROUS MATERIAL
Layer 2:	Joint Compound			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-002	05/30/23	1-2	Main Office NW Corner		
Layer 1:	Drywall			No Asbestos Detected	5% CELLULOSE FIBER
	White, Powdery				95% NON FIBROUS MATERIAL
Layer 2:	Joint Compound			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-003	05/30/23	1-3	Office Next To Bathroom		
Layer 1:	Drywall			No Asbestos Detected	5% CELLULOSE FIBER
	White, Powdery				95% NON FIBROUS MATERIAL
Layer 2:	Joint Compound			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-004	05/30/23	1-4	2nd FL Office N Wall		
Layer 1:	Drywall			No Asbestos Detected	5% CELLULOSE FIBER
	White, Powdery				95% NON FIBROUS MATERIAL
Layer 2:	Joint Compound			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-005	05/30/23	1-5	Lab SE Corner Wall		
Layer 1:	Drywall			No Asbestos Detected	8% CELLULOSE FIBER
	White, Powdery				92% NON FIBROUS MATERIAL
Layer 2:	Joint Compound			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-006	05/30/23	2-1	Main Office E Side Middle		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Light Gray/Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Soft				
519082-007	05/30/23	2-2	Main Office E Side N		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Light Gray/Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Soft				
519082-008	05/30/23	3-1	Main Office Near Entry		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Soft				
519082-009	05/30/23	3-2	Main Office Near Entry		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Soft				
519082-010	05/30/23	4-1	Main Office		
Layer 1:	Carpet Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Soft				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-011	05/30/23	4-2	2nd FL Office		
Layer 1:	Carpet Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Soft				
519082-012	05/30/23	5-1	Main Office SE Area		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-013	05/30/23	5-2	Main Office NE Area		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-014	05/30/23	5-3	Main Office W Side		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-015	05/30/23	6-1	Open Area Outside Lab E		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Bituminous				
519082-016	05/30/23	6-2	Open Area Outside Lab N		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Bituminous				
519082-017	05/30/23	7-1	Open Area Outside Lab NW		
Layer 1:	Floor Tile			2% CHRYSOTILE	98% NON FIBROUS MATERIAL
	Brown, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Brittle				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-018	05/30/23	7-2	Open Area Outside Lab NW		
Layer 1:	Floor Tile			2% CHRYSOTILE	98% NON FIBROUS MATERIAL
	Brown, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Brittle				
519082-019	05/30/23	8-1	Mechanical Room		
Layer 1:	Sheet Flooring			No Asbestos Detected	40% CELLULOSE FIBER
	Black, Org.Bound/Bituminous/Fibrous				60% NON FIBROUS MATERIAL
Sample was inhomogenous, subsamples of each component were analyzed separately.					
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Soft				
519082-020	05/30/23	8-2	Mechanical Room		
Layer 1:	Sheet Flooring			No Asbestos Detected	40% CELLULOSE FIBER
	Black, Org.Bound/Bituminous/Fibrous				60% NON FIBROUS MATERIAL
Sample was inhomogenous, subsamples of each component were analyzed separately.					
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Soft				
519082-021	05/30/23	9-1	Mechanical Room		
Layer 1:	Flue Cement			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular				
519082-022	05/30/23	9-2	Mechanical Room		
Layer 1:	Flue Cement			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular				
519082-023	05/30/23	10-1	Lab E Side		
Layer 1:	Desktop and Sides			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Hard				
519082-024	05/30/23	10-2	Lab E Side		
Layer 1:	Desktop and Sides			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Hard				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-025	05/30/23	11-1	Lab NW Sink		
Layer 1:	Undercoating			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular				
519082-026	05/30/23	11-2	Lab SW Sink		
Layer 1:	Undercoating			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular				
519082-027	05/30/23	12-1	Lab S Side		
Layer 1:	Counter Top			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Hard				
519082-028	05/30/23	12-2	Lab N Side		
Layer 1:	Counter Top			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Hard				
519082-029	05/30/23	13-1	Lab S Side		
Layer 1:	Seam Filler			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Rubbery				
519082-030	05/30/23	13-2	Lab N Side		
Layer 1:	Seam Filler			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Black, Rubbery				
519082-031	05/30/23	14-1	2nd FL SW Most Addition W		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Rubbery				
519082-032	05/30/23	14-2	2nd FL SW Most Addition E		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Rubbery				
519082-033	05/30/23	15-1	Mechanical Room N Wall		
Layer 1:	Paint			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Silver, Brittle				
519082-034	05/30/23	15-2	Mechanical Room E Wall		
Layer 1:	Paint			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Silver, Brittle				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-035	05/30/23	16-1	2nd FL SW Most Addition N		
Layer 1: Caulking White, Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Mortar Gray, Hard/Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-036	05/30/23	16-2	2nd FL SW Most Addition N		
Layer 1: Caulking White, Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Mortar Gray, Hard/Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-037	05/30/23	17-1	2nd FL SW Most Addition N		
Layer 1: Caulking White, Granular				No Asbestos Detected	5% CELLULOSE FIBER 95% NON FIBROUS MATERIAL
519082-038	05/30/23	17-2	2nd FL SW Most Addition S		
Layer 1: Caulking White, Granular				No Asbestos Detected	5% CELLULOSE FIBER 95% NON FIBROUS MATERIAL
519082-039	05/30/23	18-1	2nd FL SW Most Addition N		
Layer 1: Window Glazing Gray, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-040	05/30/23	18-2	2nd FL SW Middle Room N		
Layer 1: Window Glazing Gray, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-041	05/30/23	19-1	2nd FL SW Middle Room W		
Layer 1: Caulking Tan, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-042	05/30/23	19-2	2nd FL SW Middle Room E		
Layer 1: Caulking Tan, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-043	05/30/23	20-1	2nd FL Storage Room W		
Layer 1: Window Glazing Tan, Granular				No Asbestos Detected	2% CELLULOSE FIBER 98% NON FIBROUS MATERIAL

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-044	05/30/23	20-2	2nd FL Mezz. SW Area W		
Layer 1:	Window Glazing			No Asbestos Detected	2% CELLULOSE FIBER
	Tan, Granular				98% NON FIBROUS MATERIAL
519082-045	05/30/23	21-1	SE Mechanical Room NE		
Layer 1:	Ceiling Tile			No Asbestos Detected	90% CELLULOSE FIBER
	White/Brown, Fibrous				10% NON FIBROUS MATERIAL
519082-046	05/30/23	21-2	SE Mechanical Room NW		
Layer 1:	Ceiling Tile			No Asbestos Detected	90% CELLULOSE FIBER
	White/Brown, Fibrous				10% NON FIBROUS MATERIAL
519082-047	05/30/23	22-1	SE Mechanical Room N		
Layer 1:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Soft				
Layer 2:	Wall Paneling			No Asbestos Detected	95% CELLULOSE FIBER
	Tan, Fibrous				5% NON FIBROUS MATERIAL
519082-048	05/30/23	22-2	SE Mechanical Room N		
Layer 1:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Brown, Soft				
Layer 2:	Wall Paneling			No Asbestos Detected	95% CELLULOSE FIBER
	Tan, Fibrous				5% NON FIBROUS MATERIAL
519082-049	05/30/23	23-1	Office Next To Restroom N		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-050	05/30/23	23-2	Office Next To Restroom		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-051	05/30/23	23-3	Office Next To Restroom		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-052	05/30/23	24-1	Restroom W Side		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-053	05/30/23	24-2	Restroom Middle		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-054	05/30/23	24-3	Restroom E Side		
Layer 1:	Ceiling Texture			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-055	05/30/23	25-1	Restroom Near Door N Side		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Brittle				
519082-056	05/30/23	25-2	Restroom Near Door S Side		
Layer 1:	Floor Tile			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Organically Bound				
Layer 2:	Mastic			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Yellow, Brittle				
519082-057	05/30/23	26-1	SE Mechanical Room N		
Layer 1:	Window Glazing			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Granular				
519082-058	05/30/23	26-2	SE Mechanical Room N		
Layer 1:	Window Glazing			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Tan, Granular				
519082-059	05/30/23	27-1	Attic N		
Layer 1:	Insulation			No Asbestos Detected	90% CELLULOSE FIBER
	Gray, Fibrous				5% MINERAL/GLASS WOOL
					5% NON FIBROUS MATERIAL
519082-060	05/30/23	27-2	Attic S		
Layer 1:	Insulation			No Asbestos Detected	90% CELLULOSE FIBER
	Gray, Fibrous				5% MINERAL/GLASS WOOL
					5% NON FIBROUS MATERIAL
519082-061	05/30/23	27-3	Attic Middle		
Layer 1:	Insulation			No Asbestos Detected	90% CELLULOSE FIBER
	Gray, Fibrous				5% MINERAL/GLASS WOOL
					5% NON FIBROUS MATERIAL

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-062	05/30/23	28-1	SE Mechanical Room W		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-063	05/30/23	28-2	SE Mechanical Room E		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-064	05/30/23	28-3	SE Mechanical Room S		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-065	05/30/23	28-4	Work Shop E Wall		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	100% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-066	05/30/23	28-5	Work Shop S Wall		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	2% CELLULOSE FIBER 98% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-067	05/30/23	28-6	NE Large Bay E Wall		
Layer 1: Plaster Gray, Hard				No Asbestos Detected	2% FIBERGLASS 98% NON FIBROUS MATERIAL
Layer 2: Coating White, Granular				No Asbestos Detected	100% NON FIBROUS MATERIAL

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-068	05/30/23	28-7	NE Large Bay W Wall		
Layer 1:	Plaster			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Hard				
Layer 2:	Coating			No Asbestos Detected	100% NON FIBROUS MATERIAL
	White, Granular				
519082-069	05/30/23	29-1	Lab Near Door W Side		
Layer 1:	Floor Coating			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Cementitious				
519082-070	05/30/23	29-2	Lab Near Door E Side		
Layer 1:	Floor Coating			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Cementitious				
519082-071	05/30/23	30-1	N Bldg. Window N Side		
Layer 1:	Door Frame Caulk			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Rubbery				
519082-072	05/30/23	30-2	N Bldg. Window W Side		
Layer 1:	Door Frame Caulk			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Rubbery				
519082-073	05/30/23	31-1	N Side Basin Area		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular/Rubbery				
519082-074	05/30/23	31-2	N Side Basin Area		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Gray, Granular/Rubbery				
519082-075	05/30/23	32-1	Exterior E Side Window		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Off White, Rubbery				
519082-076	05/30/23	32-2	Exterior S Side Window		
Layer 1:	Caulking			No Asbestos Detected	100% NON FIBROUS MATERIAL
	Off White, Rubbery				

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Marysville Water Plant
Location: 409 N Main St Marysville OH
Number: 23-232-004

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
519082-077	05/30/23	33-1	Exterior S Side Office		
Layer 1: Caulking Off White, Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-078	05/30/23	33-2	Exterior S Side		
Layer 1: Caulking Off White, Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-079	05/30/23	34-1	Exterior W Side		
Layer 1: Caulking Brown/Gray, Granular/Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL
519082-080	05/30/23	34-2	Exterior W Side		
Layer 1: Caulking Brown/Gray, Granular/Rubbery				No Asbestos Detected	100% NON FIBROUS MATERIAL

EPA Regulatory Limit: 1%
Total layers analyzed on order: 108

519082-06/13/23 05:21 PM


Analyst **Thoria Nadiem**


Reviewed By: **Mohammed Hashim**
Microscopy Supervisor/Analyst

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

SCHNEIDER LABORATORIES GLOBAL, INC.

2512 West Cary Street, Richmond, Virginia 23220-5117
804-353-6778 • 800-785-LABS (5227) • Fax 804-359-1475
www.slabinc.com e-mail: info@slabinc.com

X 61

519082

V:\519\519082

aelnasseh 6/6/2023 9:10:31 AM
UPS 172F28998499671865

Submitting Co.	Dayton Environmental Testing, LLC	Lab WO #		Phone	937-751-7872
35 Compark Road		Acct #	4738	Fax / Email	Lee@DaytonTesting.com
Dayton, Ohio 45459		**State of Collection	Ohio	**Cert Required	☐ Yes ☐ No
Project Name:	Marysville Water Plant		Special Instructions [Include requests for special reporting or data packages]		
Project Location:	409 N. Main Street, Marysville, Ohio 43040		REMARKS: See Attached Asbestos Bulk Sampling Log		
Project Number:	23-232-004				
PO Number:					

Turn Around Time	Matrix / Sample Type (Select ONE)		Tests / Analysis (Select ALL that Apply)		
☐ 2 hours*	All samples on form should be of SAME <u>matrix type</u> . Use additional forms as needed.		Asbestos Air / Fiber Counts	Asbestos Bulk / Asb ID	Metals-Total Conc.
☐ Same day*			☐ PCM (NIOSH 7400)	☒ PLM (EPA 600/R-93/116)	☐ Lead
☐ 1 business day			☐ TEM (AHERA)	☐ PLM (EPA Point Count)	☐ RCRA Metals
☐ 2 business days			☐ TEM (EPA Level II)	☐ PLM (Qualitative Only)	☐ _____
☐ 3 business days	☐ Air	☐ Solid	☐ _____	☐ NYELAP 198.1/.4/.6	☐ _____
☐ 5 business days	☐ Aqueous	☐ Waste	Miscellaneous Tests	☐ CAELAP (EPA Inerim)	Metals-Extract
☒ Full TCLP (10d)	☒ Bulk	☐ Wastewater	☐ Total Dust (NIOSH 0500)	☐ TEM (Chatfield)	☐ TCLP / Lead
☐ Weekend*	☐ Hi-Vol Filter (PM10)	☐ Water, Drinking	☐ Resp. Dust (NIOSH 0600)	☐ _____	☐ TCLP / RCRA Metals
* not available for all tests	☐ Hi-Vol Filter (TSP)	☐ Compliance	☐ Silica - FTIR (NIOSH 7602)	FOR ASBESTOS AIR:	☐ TCLP / Full (w/orgainics)
Schedule rush organics, multi-metals & weekend tests in advance.	☐ Oil	☐ Wipe	☐ Silica - XRD (NIOSH 7500)	TYPE OF RESPIRATOR	Others
	☐ Paint	☐ Wipe, Composite	☐ Mold Analysis	USED: _____	
	☐ Sludge	☐ _____			
	☐ Soil	☐ _____			

[illegible]

¹Type: A=area B=blank P=personal E=excursion ²Beginning/End of Sample Period ³ Pump Calibration in Liters/Minute ⁴Volume in Liters [time in min * flow in L/min]

Sampled by Name: Michael Lee Signature  Date/Time: 5/30/2023 @ 11:30		Relinquished to lab by Name: Michael Lee Signature  Date/Time: 5/30/2023 @ 20:00		☐ Receive a physical copy of report	Sample Disposal: ☐ Return to Sender ☐ Disposal by lab
☐ Sample Return Requested ☐ Ambient temp ☐ Ice ___ ☐ CI ___ ☐ R ☐ S ☐ X		Shipping Methods ☐ UPS ☐ FX ☐ USM ☐ HD ☐ DE			

*Temperature taken with IR Gun A. **Required. Chain-of-Custody documentation continued internally within lab. Terms and conditions page 2.

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
1-1	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Main Office, Southeast Corner Wall	M. Lee
1-2	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Main Office, Northwest Corner Wall	M. Lee
1-3	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Office (Next to Bathroom), Southeast Corner Wall	M. Lee
1-4	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	2nd Floor Office, North Wall, Middle	M. Lee
1-5	1	5/30/2023	Drywall Board and Joint Compound	White Drywall Board with White Joint Compound	Laboratory, Southeast Corner Wall	M. Lee
2-1	2	5/30/2023	Floor Tile and Mastic	12" x 12" Light Gray with Tan Streaks Floor Tile and Yellow Mastic	Main Office, East Side, Middle	M. Lee
2-2	2	5/30/2023	Floor Tile and Mastic	12" x 12" Light Gray with Tan Streaks Floor Tile and Yellow Mastic	Main Office, East Side, North	M. Lee
3-1	3	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Yellow Mastic	Main Office, Near Entry Door	M. Lee
3-2	3	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Yellow Mastic	Main Office, Near Entry Door	M. Lee
4-1	4	5/30/2023	Carpet Mastic	Tan Mastic Associated with Carpeting	Main Office	M. Lee
4-2	4	5/30/2023	Carpet Mastic	Tan Mastic Associated with Carpeting	2nd Floor Office	M. Lee
5-1	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, Southeast Area	M. Lee
5-2	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, Northeast Area	M. Lee
5-3	5	5/30/2023	Texture Compound	White Ceiling Texture Compound	Main Office, West Side	M. Lee
6-1	6	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Mottled Floor Tile and Black Mastic	Open Area Outside Laboratory, East Side	M. Lee
6-2	6	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Mottled Floor Tile and Black Mastic	Open Area Outside Laboratory, North Side	M. Lee
7-1	7	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Brown Mastic	Open Area Outside Laboratory, Northwest Area	M. Lee
7-2	7	5/30/2023	Floor Tile and Mastic	12" x 12" Brown Mottled Floor Tile with Brown Mastic	Open Area Outside Laboratory, Northwest Area	M. Lee
8-1	8	5/30/2023	Sheet Flooring and Mastic	Black Sheet Flooring and Brown Mastic	Mechanical Room	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
8-2	8	5/30/2023	Sheet Flooring and Mastic	Black Sheet Flooring and Brown Mastic	Mechanical Room	M. Lee
9-1	9	5/30/2023	Flue Cement	Gray Flue Cement	Mechanical Room	M. Lee
9-2	9	5/30/2023	Flue Cement	Gray Flue Cement	Mechanical Room	M. Lee
10-1	10	5/30/2023	Desktop	Black Desktop and Sides	Laboratory, East Side	M. Lee
10-2	10	5/30/2023	Desktop	Black Desktop and Sides	Laboratory, East Side	M. Lee
11-1	11	5/30/2023	Sink Undercoating	Gray Sink Undercoating	Laboratory, Northwest Sink	M. Lee
11-2	11	5/30/2023	Sink Undercoating	Gray Sink Undercoating	Laboratory, Southwest Sink	M. Lee
12-1	12	5/30/2023	Laboratory Counters	Black Laboratory Countertop, Backsplash, and Drywall Rack	Laboratory, South Side	M. Lee
12-2	12	5/30/2023	Laboratory Counters	Black Laboratory Countertop, Backsplash, and Drywall Rack	Laboratory, North Side	M. Lee
13-1	13	5/30/2023	Filler	Black Seam Filler Associated with Laboratory Countertop	Laboratory, South Side	M. Lee
13-2	13	5/30/2023	Filler	Black Seam Filler Associated with Laboratory Countertop	Laboratory, North Side	M. Lee
14-1	14	5/30/2023	Caulking	Tan Rubbery Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Most Addition, West Side	M. Lee
14-2	14	5/30/2023	Caulking	Tan Rubbery Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Most Addition, East Side	M. Lee
15-1	15	5/30/2023	Paint	Silver Paint	Mechanical Room, North Wall	M. Lee
15-2	15	5/30/2023	Paint	Silver Paint	Mechanical Room, East Wall	M. Lee
16-1	16	5/30/2023	Caulking and Mortar	White Caulking and Gray Mortar Associated with Steel Window Frames	2nd Floor, Southwest Most Addition, North Wall, West Side	M. Lee
16-2	16	5/30/2023	Caulking and Mortar	White Caulking and Gray Mortar Associated with Steel Window Frames	2nd Floor, Southwest Most Addition, North Wall, East Side	M. Lee
17-1	17	5/30/2023	Caulking	White Caulking Associated with Steel Window Frames	2nd Floor, Southwest Middle Room, North Wall	M. Lee
17-2	17	5/30/2023	Caulking	White Caulking Associated with Steel Window Frames	2nd Floor, Southwest Middle Room, South Wall	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
18-1	18	5/30/2023	Window Glazing Compound	Gray Window Glazing Compound	2nd Floor, Southwest Most Addition, North Wall, West Side	M. Lee
18-2	18	5/30/2023	Window Glazing Compound	Gray Window Glazing Compound	2nd Floor, Southwest Middle Room, North Wall	M. Lee
19-1	19	5/30/2023	Caulking	Tan Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Middle Room, West Side	M. Lee
19-2	19	5/30/2023	Caulking	Tan Caulking Associated with Concrete Ceiling Joints	2nd Floor, Southwest Middle Room, East Side	M. Lee
20-1	20	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	2nd Floor Storage Room, West Wall	M. Lee
20-2	20	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	2nd Floor Mezzanine (Southwest Area), West Wall	M. Lee
21-1	21	5/30/2023	Ceiling Tile	2' x 4' Ceiling Tile (Brown with White Face)	Southeast Mechanical Room, Northeast Side	M. Lee
21-2	21	5/30/2023	Ceiling Tile	2' x 4' Ceiling Tile (Brown with White Face)	Southeast Mechanical Room, Northwest Area	M. Lee
22-1	22	5/30/2023	Mastic	Brown Mastic Associated with Wall Paneling	Southeast Mechanical Room, North Wall, West Side	M. Lee
22-2	22	5/30/2023	Mastic	Brown Mastic Associated with Wall Paneling	Southeast Mechanical Room, North Wall, East Side	M. Lee
23-1	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Northwest Area	M. Lee
23-2	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Middle Area	M. Lee
23-3	23	5/30/2023	Texture Compound	White Ceiling Texture Compound (Stomp Pattern)	Office (Next to Restroom) Southeast Area	M. Lee
24-1	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, West Side	M. Lee
24-2	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, Middle	M. Lee
24-3	24	5/30/2023	Texture Compound	White Ceiling Texture Compound (Light Texture)	Restroom, East Side	M. Lee
25-1	25	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Speckled Floor Tile with Yellow Mastic	Restroom (Near Door, North Side)	M. Lee
25-2	25	5/30/2023	Floor Tile and Mastic	12" x 12" Tan Speckled Floor Tile with Yellow Mastic	Restroom (Near Door, South Side)	M. Lee
26-1	26	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	Southeast Mechanical Room, North Wall, East Side	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant
409 N. Main Street, Marysville, Ohio 43040
Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
26-2	26	5/30/2023	Window Glazing Compound	Tan Window Glazing Compound	Southeast Mechanical Room, North Wall, West Side	M. Lee
27-1	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic (North)	M. Lee
27-2	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic (South)	M. Lee
27-3	27	5/30/2023	Attic Insulation	Gray Attic Insulation (Loose)	Attic, Middle	M. Lee
28-1	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, West Wall	M. Lee
28-2	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, East Wall	M. Lee
28-3	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Southeast Mechanical Room, South Wall	M. Lee
28-4	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Work Shop, East Wall	M. Lee
28-5	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Work Shop, South Wall	M. Lee
28-6	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Northeast Large Bay, East Wall	M. Lee
28-7	28	5/30/2023	Plaster	Hard Plaster (White Finish Coat over Gray Base Coat)	Northeast Large Bay, West Wall	M. Lee
29-1	29	5/30/2023	Floor Coating	Gray Floor Coating (Cementitious)	Laboratory (Near Door, West Side)	M. Lee
29-2	29	5/30/2023	Floor Coating	Gray Floor Coating (Cementitious)	Laboratory (Near Door, East Side)	M. Lee
30-1	30	5/30/2023	Caulking	Gray Window and Door Frame Caulking	North Building Window, North Side	M. Lee
30-2	30	5/30/2023	Caulking	Gray Window and Door Frame Caulking	North Building Window, West Side	M. Lee
31-1	31	5/30/2023	Caulking	Gray Caulking Sealant	North Side Basin Area	M. Lee
31-2	31	5/30/2023	Caulking	Gray Caulking Sealant	North Side Basin Area	M. Lee
32-1	32	5/30/2023	Caulking	Off-White Caulking Associated with Newer Windows	Exterior, East Side Window	M. Lee
32-2	32	5/30/2023	Caulking	Off-White Caulking Associated with Newer Windows	Exterior, South Side Window	M. Lee

Asbestos Bulk Sampling Log

Limited Asbestos Sampling - Marysville Water Plant

409 N. Main Street, Marysville, Ohio 43040

Project Number: 23-232-004

Sample #	Group #	Collection Date	Material	Color/Description	Sample Location	Collected By
33-1	33	5/30/2023	Caulking	Off-White Caulking Associated with Doors	Exterior, South Side Office Door	M. Lee
33-2	33	5/30/2023	Caulking	Off-White Caulking Associated with Doors	Exterior, South Side Mechanical Room Door	M. Lee
34-1	34	5/30/2023	Caulking	Brown and Gray Caulking Associated with Door	Exterior, West Side Door	M. Lee
34-2	34	5/30/2023	Caulking	Brown and Gray Caulking Associated with Door	Exterior, West Side Door	M. Lee

ATTACHMENT E
PHOTOGRAPHS



Photograph 1



Photograph 2



Photograph 3



Photograph 4



Photograph 5



Photograph 6



Photograph 7



Photograph 8




Photograph 9



Photograph 10



Photograph 11



Photograph 12



Photograph 13



Photograph 14



Photograph 15



Photograph 16




Photograph 17



Photograph 18



Photograph 19



Photograph 20



Photograph 21



Photograph 22



Photograph 23



Photograph 24



Photograph 25



Photograph 26



Photograph 27



Photograph 28



Photograph 29



Photograph 30



Photograph 31



Photograph 32



Photograph 33



Photograph 34



Photograph 35



Photograph 36



Photograph 37



Photograph 38



Photograph 39



Photograph 40

ATTACHMENT F
QUALIFICATIONS OF ASSESSOR



Mike DeWine, Governor
Jon Husted, Lt. Governor
Anne M. Vogel, Director

2/15/2023

Michael Lee
Michael B. Lee
P.O. Box 1084
Marysville, OH 43040

RE: Evaluation Specialist
Certification Number: ES34954
Expiration Date: 3/10/2024

Dear Michael Lee:

This letter and enclosed certification card approves your request to be certified as an asbestos Evaluation Specialist. You must present your card upon request at any project site while performing duties. Copies of cards are not acceptable as proof of certification.

This certification may be revoked by the Director of the Ohio Environmental Protection Agency (EPA) for violation of any of the requirements of 3745-22 or 3745-20 of the Ohio Administrative Code.

If you have any questions, please contact the Asbestos Program at 614-644-0226 or by email at asbestoslicensing@epa.ohio.gov.


Sincerely,

Brandon M. Schwendeman
Brandon Schwendeman
Manager, Business Operations Support Section
Ohio EPA - Division of Air Pollution Control



ATTACHMENT G
LABORATORY'S NVLAP CERTIFICATE

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2017

NVLAP LAB CODE: 101150-0

Schneider Laboratories Global, Inc.

Richmond, VA

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:*

Asbestos Fiber Analysis

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2017.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).*

2023-04-01 through 2024-03-31

Effective Dates



A handwritten signature in blue ink, reading "Dana S. Laman".

For the National Voluntary Laboratory Accreditation Program